



**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS,
BALLOONS, & AIRSHIPS**

BIWEEKLY 2004-04

This electronic copy may be printed and used in lieu of the FAA biweekly paper copy.

U.S. Department of Transportation
Federal Aviation Administration
Regulatory Support Division
Delegation and Airworthiness Programs Branch, AIR-140
P. O. Box 26460
Oklahoma City, OK 73125-0460
FAX 405-954-4104

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; - See AD for additional information;

Biweekly 2004-01

2003-23-05	COR	Titeflex Corportation	Appliance: Titeflex hoses
2003-24-13	COR	Cessna Aircraft Company	172R, 172S, 182S, 182T, T182T, 206H, and T206H
2003-26-04		Agusta S.p.A.	Rotorcraft: A109E
2003-26-06		Anjou Aeronautique	Appliance: Safety belts and restraint systems
2003-26-14		Kiddie Aerospace	Appliance: Hand-held halon fire extinguishers
2004-01-09		Eurocopter France	Rotorcraft: AS355E, F, F1, F2, and N
2004-01-10		Eurocopter Deutschland	Rotorcraft: MBB-BK-117 A-1, A-3, A-4, B-1, B-2, and C-1
2004-01-14		Eurocopter France	Rotorcraft: EC130B4
2004-01-51	E	Eurocopter France	Rotorcraft: AS355E, F, F1, F2, and N

Biweekly 2004-02

2003-09-09 R1	R	Cessna Aircraft Company	441 and F406
2004-01-13	S 97-22-16	Raytheon Aircraft Company	1900, 1900C, 1900 (C-12J), and 1900D

Biweekly 2004-03

2004-02-03		Agusta S.p.A.	Rotorcraft: A109E
2004-03-01	S 2003-03-11	Air Cruisers Company	Appliance: Emergency Evacuation Slide/Raft Systems

Biweekly 2004-04

2004-03-08		Learjet	31, 31A, 35, 35A (C-21A), 36 and 36A
2004-03-27	COR	Eurocopter France	Rotorcraft: AS332C, L, and L1
2004-03-29		Pacific Aerospace Corporation, Ltd.	FU24-954 and FU24A-954
2004-03-32		The New Piper Aircraft, Inc.	PA-46-500TP
2004-04-01	S 2002-01-09	Pilatus Aircraft LTD.	PC-7, PC-12, and PC-12/45

BW 2004-04

**LEARJET
AIRWORTHINESS DIRECTIVE
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

2004-03-08 Learjet: Amendment 39-13452. Docket 2001-NM-366-AD.

Applicability: The following airplanes, certificated in any category, as applicable:

Table 1.—Applicability

Model—	As Listed in Bombardier Service Bulletin—
31 and 31A Airplanes	31-51-2, dated February 1, 2001; and 31-51-3, Revision 1, dated August 2, 2001.
35, 35A (C-21A), 36 and 36A Airplanes	35/36-51-3, dated February 1, 2001; and 35/36-51-4, Revision 1, dated August 2, 2001.

Compliance: Required as indicated, unless accomplished previously.

To prevent significant structural damage to the engine pylons, possible separation of the engines from the fuselage, and consequent reduced controllability of the airplane, accomplish the following:

Inspections

(a) At the later of the times specified in paragraphs (a)(1) and (a)(2) of this AD: Do a detailed inspection (using a probe) and a general visual inspection of the shear webs of the forward engine beams (including modification of the drag angles) for cracking in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 31-51-2 (for Model 31 airplanes) or 35/36-51-3 (for Model 35 and 36 airplanes), both dated February 1, 2001; as applicable.

(1) Prior to the accumulation of 3,000 total flight hours; or

(2) Within 1,200 flight hours or 1 year after the effective date of this AD, whichever occurs first.

Note 1: For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to enhance visual access to all exposed surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

Note 2: For the purposes of this AD, a detailed inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at

intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

Detailed Probe Inspection Follow-On Actions

(b) Following the detailed probe inspection required by paragraph (a) of this AD, do the follow-on actions specified in paragraphs (b)(1), (b)(2), or (b)(3) of this AD, as applicable, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 31-51-2 or 35/36-51-3, both dated February 1, 2001; as applicable.

(1) If the resistance measured during the inspection is less than 0.110 milliohm: Repeat the inspections required by paragraph (a) of this AD thereafter at intervals not to exceed 1,200 flight hours.

(2) If the resistance measured during the inspection is 0.110 milliohm or more, but less than 0.150 milliohm: Within the next 1,200 flight hours, repair and modify the forward engine beam shear web in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 31-51-3, Revision 1 (for Model 31 airplanes) or 35/36-51-4, Revision 1 (for Model 35 and 36 airplanes), both dated August 2, 2001; as applicable.

(3) If the resistance measured during the inspection is 0.150 milliohm or more: Before further flight, repair and modify the forward engine beam shear web in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 31-51-3, Revision 1, or 35/36-51-4, Revision 1; as applicable.

General Visual Inspection Follow-On Actions

(c) Following the general visual inspection required by paragraph (a) of this AD, do all of the applicable follow-on actions at the times specified in the Accomplishment Instructions of Bombardier Service Bulletin 31-51-2 or 35/36-51-3, both dated February 1, 2001; as applicable; except as specified in paragraph (d) of this AD.

(d) If any crack opening is found that is more than 0.03 inch during the general visual inspection required by paragraph (a) of this AD: Before further flight, do the actions specified in paragraphs 2.C.(16)(a) and 2.C.(16)(b) of Bombardier Service Bulletin 31-51-2 or 35/36-51-3, both dated February 1, 2001; as applicable; repair per a method approved by the Manager, Wichita Aircraft Certification Office (ACO), FAA; and do the terminating action specified in paragraph (e) of this AD.

Terminating Action

(e) Modification of the shear webs by accomplishing all of the actions specified in the Accomplishment Instructions of Bombardier Service Bulletin 31-51-3, Revision 1, or 35/36-51-4, Revision 1, both dated August 2, 2001; as applicable; terminates the initial inspections required by paragraph (a) and the repetitive inspections required by paragraph (b)(1) of this AD.

Repair Approval

(f) Where any service bulletin identified in this AD specifies that the manufacturer may be contacted for disposition of certain repair conditions, repair per a method approved by the Manager, Wichita ACO, FAA.

Submission of Inspection Results Not Required

(g) Although the service bulletins identified in this AD specify to submit information to the manufacturer, this AD does not include such a requirement.

Alternative Methods of Compliance

(h) In accordance with 14 CFR 39.19, the Manager, Wichita ACO, is authorized to approve alternative methods of compliance for this AD.

Incorporation by Reference

(i) Unless otherwise specified in this AD, the actions shall be done in accordance with Bombardier Service Bulletin 31-51-2, dated February 1, 2001, and Bombardier Service Bulletin 31-51-3, Revision 1, dated August 2, 2001; or Bombardier Service Bulletin 35/36-51-3, dated February 1, 2001, and Bombardier Service Bulletin 35/36-51-4, Revision 1, dated August 2, 2001; as applicable. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Learjet, Inc., One Learjet Way, Wichita, Kansas 67209-2942. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(j) This amendment becomes effective on March 15, 2004.

Issued in Renton, Washington, on January 29, 2004.
Kalene C. Yanamura,
Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 04-2585 Filed 2-6-04; 8:45 am]
BILLING CODE 4910-13-P

BW 2004-04

**EUROCOPTER FRANCE
AIRWORTHINESS DIRECTIVE
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

CORRECTION: The AD number is *incorrect* in the Federal Register (FR) version, pg 7114, column 2, February 13, 2004, of this AD. It should be "2004-03-27". The FR will publish a correction in the near future. We have corrected this copy.

2004-03-27 Eurocopter France: Amendment 39-13471. Docket No. 2002-SW-45-AD.

Applicability: Model AS332C, L, and L1 helicopters, with main gearbox bevel gear (bevel gear), part numbers (P/N) 332A32-2027-00 or 332A32-2026-00, containing bevel gears, P/N 332A32-2181-00, -01, -02, -03, or -04, or 331A32-3110-07, -08, -09, or -19, installed, certificated in any category. This AD does not apply to:

- Main gearboxes that were overhauled after December 31, 2002;
- Parts inspected in accordance with AS332 letter to Repair Stations No. 183; or
- Parts repaired in accordance with Repair Sheet (F.R.) 332A32-2181-ZA or 331A32-3110-ZA.

Compliance: Required as indicated, unless accomplished previously.

To detect a bevel gear crack and prevent failure of the bevel gear, loss of torque to the main rotor system, and subsequent loss of control of the helicopter, accomplish the following:

(a) For bevel gears that have more than 6,600 hours time-in-service (TIS), within 50 hours TIS and thereafter at intervals not to exceed 150 hours TIS, or at intervals not to exceed 1,000 frequent torque variation cycles, whichever occurs first, inspect for a crack using a borescope in accordance with the Operational Procedure, paragraph 2.B.1. and 2.B.2. of Eurocopter Telex No. 05.00.58 R2, dated February 3, 2003. A frequent torque variation cycle is each landing or external load operation beginning at the point when there are 4 or more landings, or 4 or more external load operations, or any combination of 4 or more landings and external load operations in any 60 minute time period, and ending when any combination of landings and external load operations is less than 4 in any 60 minute time period.

(b) If a crack is found in the bevel gear, before further flight, replace the bevel gear with an airworthy bevel gear.

(c) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Safety Management Group, Rotorcraft Directorate, FAA, for information about previously approved alternative methods of compliance.

(d) The inspection and replacement, if necessary, shall be done in accordance with Eurocopter Telex No. 05.00.58 R2, dated February 3, 2003. The Director of the Federal Register approved this incorporation by reference in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from American Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, Texas 75053-4005, telephone (972) 641-3460, fax (972) 641-3527. Copies may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

(e) This amendment becomes effective on March 19, 2004.

Note: The subject of this AD is addressed in Direction Generale De L'Aviation Civile (France) AD 2002-424-081(A) R2, dated March 19, 2003.

Issued in Fort Worth, Texas, on January 30, 2004.

David A. Downey,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 04-2782 Filed 2-12-04; 8:45 am]

BILLING CODE 4910-13-P

BW 2004-04

**PACIFIC AEROSPACE CORPORATION, LTD.
AIRWORTHINESS DIRECTIVE
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

2004-03-29 Pacific Aerospace Corporation, Ltd.: Amendment 39-13473; Docket No. 2003-CE-38-AD.

When Does This AD Become Effective?

(a) This AD becomes effective on April 19, 2004.

What Other ADs Are Affected by This Action?

(b) None.

What Airplanes Are Affected by This AD?

(c) This AD affects Models FU24-954 and FU24A-954 airplanes, all serial numbers, that are certificated in any category.

What Is the Unsafe Condition Presented in This AD?

(d) This AD is the result of a recent fatal accident where the aircraft's fin separated in flight. The actions specified in this AD are intended to detect and correct cracks in the vertical fin base, which could result in loss of the fin or loss of control of the aircraft.

What Must I Do To Address This Problem?

(e) To address this problem, you must do the following:

Actions	Compliance	Procedures
(1) Perform visual inspection of the forward area at the base of the fin for cracks.	Initially inspect within the next 50 hours time-in-service (TIS) after April 19, 2004 (the effective date of this AD). Repetitively inspect every 100 hours TIS thereafter.	Inspect from the bottom of the fin up to the first external strap, paying particular attention to the skin in the area of the rivets that join the fin skin to the bulkhead, part number (P/N) 242305, and aft to the first vertical lap joint. To do this inspection, remove any rubber abrasion protection that is fitted in this area, including any sealant. You must also remove the fin leading edge fairing, P/N 242321.
(2) Repair any cracks that are found during the inspection.	Prior to further flight after doing any inspection required in paragraph (e)(1) of this AD.	Obtain an FAA-approved repair scheme from Pacific Aerospace Corporation, Ltd., Airport Road, Hamilton Airport, Hamilton, New Zealand and notify the FAA at the address and phone number in paragraph (f) of this AD.

May I Request an Alternative Method of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Standards Office, FAA, Small Airplane Directorate. For information on any already approved alternative methods of compliance, contact Karl Schletzbaum, Aerospace Engineer, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, MO 64106; telephone: (816) 329-4146; facsimile: (816) 329-4090.

Is There Other Information That Relates to This Subject?

(g) CAA airworthiness directive DCA/FU24/173, dated April 23, 2002, also addresses the subject of this AD.

Issued in Kansas City, Missouri, on February 4, 2004.
Dorenda D. Baker,
Manager, Small Airplane Directorate, Aircraft Certification Service.
[FR Doc. 04-2953 Filed 2-10-04; 8:45 am]
BILLING CODE 4910-13-U

BW 2004-04

**THE NEW PIPER AIRCRAFT, INC.
AIRWORTHINESS DIRECTIVE
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

2004-03-32 The New Piper Aircraft, Inc.: Amendment 39-13476; Docket No. 2003-CE-32-AD.

When Does This AD Become Effective?

(a) This AD becomes effective on March 29, 2004.

What Other ADs Are Affected by This Action?

(b) None.

What Airplanes Are Affected by This AD?

(c) This AD affects Model PA-46-500TP airplanes, serial numbers 4697001 through 4697140 and 4697142 through 4697153, that are certificated in any category.

What Is the Unsafe Condition Presented in This AD?

(d) This AD is the result of reports of smoke in the cockpit and loss of electrical system functions. We are issuing this AD to prevent short circuit failure of the electronic control modules, which could result in loss of the electrical system components or burning of wiring insulation and cause smoke in the cockpit. This condition could lead to the inability to properly control the airplane.

What Must I Do To Address This Problem?

(e) To address this problem, you must do the following:

Actions	Compliance	Procedures
(1) Remove the following parts: (i) the pilot's circuit breaker panel assembly (part-number (P/N) 102228-002); (ii) the co-pilot's circuit breaker panel assembly (P/N 102228-006); (iii) the dimmer lighting module assembly (P/N 102226-002); (iv) the stall vane heat module assembly (P/N 102227-002); and (v) the propeller heat module assembly (P/N 102227-006).	Within the next 100 hours time-in-service (TIS) after March 29, 2004 (the effective date of this AD).	Follow the instructions in Piper Service Bulletin No. 1132, dated June 4, 2003.

(2) Return the circuit breaker panels and the remote modules identified in paragraph (e)(1) of this AD to the manufacturer listed in paragraph (g) of this AD for modification.	Prior to further flight after doing the actions required in paragraph (e)(1) of this AD.	Follow the instructions in Piper Service Bulletin No. 1132, dated June 4, 2003.
(3) Visually inspect all remaining exposed wires and equipment for evidence of heat damage and repair any damage found.	Prior to further flight after doing the actions required in paragraph (e)(1) of this AD.	Follow the instructions in Piper Service Bulletin No. 1132, dated June 4, 2003.
(4) Install the modified circuit breaker panel assemblies and the remote modules received from the manufacturer.	Prior to further flight after doing the actions required in paragraphs (e)(1), (e)(2), and (e)(3) of this AD.	Follow the instructions in Piper Service Bulletin No. 1132, dated June 4, 2003.
(5) Do not install any part referenced in paragraph (e)(1) of this AD unless it has been modified per Piper Service Bulletin No. 1132, dated June 4, 2003.	As of March 29, 2004 (the effective date of this AD).	Not applicable.

May I Request an Alternative Method of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Atlanta Aircraft Certification Office (ACO), FAA. For information on any already approved alternative methods of compliance, contact Kenneth B. Mobley, Aerospace Engineer, FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, Suite 450, Atlanta, Georgia 30349; telephone: (770) 703-6046; facsimile: (770) 703-6097.

Does This AD Incorporate Any Material by Reference?

(g) You must do the actions required by this AD following the instructions in Piper Service Bulletin No. 1132, dated June 4, 2003. The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. You may get a copy from The New Piper Aircraft, Inc., Customer Services, 2926 Piper Drive, Vero Beach, Florida 32960; telephone: (772) 567-4361; facsimile: (772) 978-6584. You may review copies at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Issued in Kansas City, Missouri, on February 5, 2004.

Dorenda D. Baker,
Manager, Small Airplane Directorate, Aircraft Certification Service.
[FR Doc. 04-3050 Filed 2-17-04; 8:45 am]
BILLING CODE 4910-13-U

BW 2004-04

PILATUS AIRCRAFT LTD. AIRWORTHINESS DIRECTIVE SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

2004-04-01 Pilatus Aircraft LTD.: Amendment 39-13481; Docket No. 2003-CE-45-AD;
Supersedes AD 2002-01-09, Amendment 39-12600.

When Does This AD Become Effective?

- (a) This AD becomes effective on March 29, 2004.

What Other ADs Are Affected by This Action?

- (b) This AD supersedes AD 2002-01-09, Amendment 39-12600.

What Airplanes Are Affected by This AD?

- (c) This AD affects the following airplane models and serial numbers that are certificated in any category:

Model	Serial numbers
(1) PC-7	All manufacturer serial numbers (MSN) equipped with either a Lear Romec part number (P/N) RG9570M (Pilatus P/N 968.84.51.103) engine-driven pump or a Lear Romec P/N RG9570M1 (Pilatus P/N 968.84.51.105) engine-driven pump.
(2) PC-12 and PC-12/45	All MSN equipped with a Lear Romec P/N RG9570R1 (Pilatus P/N 968.84.51.106) engine-driven pump.

Note: Pilatus installed these engine-driven pumps on MSN 101 through MSN 406 and MSN 408 through 419 of the Models PC-12 and PC-12/45 airplanes and MSN 101 through MSN 618 of the Model PC-7 airplanes. These engine-driven pumps could be installed through field approval on any MSN of the Models PC-7, PC-12, and PC-12/45 airplanes.

What Is the Unsafe Condition Presented in This AD?

- (d) The actions specified in this AD are intended to detect and correct gasket material extruding from the engine-driven pump housing and detect and correct relief valve attachment screws with inadequate torque. These conditions could lead to fuel leakage and result in a fire in the engine compartment.

What Must I Do To Address This Problem?

- (e) To address this problem, you must do the following:

(1) Inspection: Inspect the joints between the engine-driven pump housing, the relief valve housing, and the relief valve cover for signs of fuel leakage and extruding gasket material as follows:

Engine-driven pump P/N	Compliance	Procedures
(i) Lear Romec P/N RG9570M1 (Pilatus P/N 968.84.51.105) or Lear Romec P/N RG9570R1 (Pilatus P/N 968.84.51.106).	Within the next 20 hours time-in-service (TIS) after February 28, 2002 (the effective date of AD 2002-01-09) or within the next 30 days after February 28, 2002 (the effective date of AD 2002-01-09), whichever occurs first, unless already done.	Follow Pilatus PC-7 Service Bulletin No. 28-006 or Pilatus PC-12 Service Bulletin No. 28-009, both dated August 10, 2001, as applicable.
(ii) Lear Romec P/N RG9570M (Pilatus P/N 968.84.51.103).	Within the next 20 hours TIS after March 29, 2004 (the effective date of this AD) or within 30 days after March 29, 2004 (the effective date of this AD), whichever occurs first, unless already done.	Follow Pilatus PC-7 Service Bulletin No. 28-008, Revision 1, dated September 24, 2002.

(2) Replacement/Modification: Replace the engine-driven pump with one of the following before further flight after the inspection in paragraph (e)(1) of this AD if you find signs of fuel leakage or extruding gasket material or within 6 months after March 29, 2004 (the effective date of this AD) if you do not find signs of fuel leakage or extruding gasket material, unless already done:

Models	Pump replacement P/N	Procedures
(i) PC-7	LearRomec P/N RG9570M1/M(Pilatus P/N 968.84.51.107).	Pilatus PC-7 Service Bulletin No. 28-007, Revision No. 1, dated October 1, 2002.
(ii) PC-12 and PC-12/45	Lear Romec P/N RG9570R1/M(Pilatus P/N 968.84.51.108).	Pilatus PC-12 Service Bulletin No. 28-010, and dated September 16, 2002.

(3) Relief Valve Attachment Screw Torque: Before further flight after the inspection (if you find no fuel leakage or extruding gasket material) and replacement required by this AD, ensure that the relief valve attachment screws are adequately torqued and re-torqued as necessary using the following:

(i) For Pilatus Model PC-7 Airplanes: Pilatus PC-7 Service Bulletin No. 28-006, dated August 10, 2001, or Pilatus PC-7 Service Bulletin No. 28-008, Revision 1, dated September 24, 2002.

(ii) For Pilatus Models PC-12 and PC-12/45 Airplanes: Pilatus PC-12 Service Bulletin No. 28-009, dated August 10, 2001.

(4) Spares: As of March 29, 2004 (the effective date of this AD), install only an engine-driven pump that is a part number referenced in paragraphs (e)(2)(i) and (e)(2)(ii) of this AD. Before further flight after installation, do the relief valve attachment screw torque check as required by paragraph (e)(3) of this AD.

(5) Unless Already Done Credit: This AD retains actions from AD 2002-01-09.

(i) You may take inspection credit if you have one of the engine-driven pumps installed affected by AD 2002-01-09 and the specific actions are already done.

(ii) The actions of this AD do not apply if you have one of the engine-driven pumps installed that is referenced in paragraphs (e)(2)(i) and (e)(2)(ii) of this AD.

May I Request an Alternative Method of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Standards Office, Small Airplane Directorate, FAA. For information on any already approved alternative methods of compliance, contact Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; facsimile: (816) 329-4090.

Does This AD Incorporate Any Material by Reference?

(g) You must do the actions required by this AD following Pilatus PC-7 Service Bulletin No. 28-006 and Pilatus PC-12 Service Bulletin No. 28-009, both dated August 10, 2001; Pilatus PC-7 Service Bulletin No. 28-007, Revision No. 1, dated October 1, 2002; Pilatus PC-7 Service Bulletin No. 28-008, Revision 1, dated September 24, 2002; and Pilatus PC-12 Service Bulletin No. 28-010, dated September 16, 2002.

(1) On February 28, 2002 (67 FR 2323, January 17, 2002), and in accordance with 5 U.S.C. 552(a) and 1 CFR part 51, the Director of the Federal Register approved the incorporation by reference of Pilatus PC-7 Service Bulletin No. 28-006 and Pilatus PC-12 Service Bulletin No. 28-009, both dated August 10, 2001.

(2) As of March 29, 2004, and in accordance with 5 U.S.C. 552(a) and 1 CFR part 51, the Director of the Federal Register approved the incorporation by reference of Pilatus PC-7 Service Bulletin No. 28-007, Revision No. 1, dated October 1, 2002; Pilatus PC-7 Service Bulletin No. 28-008, Revision 1, dated September 24, 2002; and Pilatus PC-12 Service Bulletin No. 28-010, dated September 16, 2002.

(3) You may get a copy of these documents from Pilatus Aircraft Ltd., Customer Liaison Manager, CH-6371 Stans, Switzerland; telephone: +41 41 619 63 19; facsimile: +41 41 619 6224; or from Pilatus Business Aircraft Ltd., Product Support Department, 11755 Airport Way, Broomfield, Colorado 80021; telephone: (303) 465-9099; facsimile: (303) 465-6040. You may review copies at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

Is There Other Information That Relates to This Subject?

(h) FOCA (Switzerland) AD HB 2003-392, dated September 15, 2003; and FOCA (Switzerland) AD HB 2003-251, dated June 16, 2003, also address the subject of this AD.

Issued in Kansas City, Missouri, on February 10, 2004.

James E. Jackson,
Acting Manager, Small Airplane Directorate, Aircraft Certification Service.
[FR Doc. 04-3351 Filed 2-17-04; 8:45 am]
BILLING CODE 4910-13-P